

**ANNUAL REPORT TO
CORVALLIS RURAL FIRE PROTECTION DISTRICT
CALENDAR YEAR 2008**

APPARATUS REPORT

The Corvallis Rural Fire District currently owns two vehicles and associated equipment:

Apparatus 146 is a 2005, 3,000-gallon International tender. This vehicle is in good to excellent condition. Maintenance costs are low, with no major breakdowns over the past year. This vehicle has served the district well with no down time due to mechanical issues. It is currently at the County Shops for yearly maintenance. This vehicle has low miles for its age and is fully expected to last its full projected service life. The vehicle's excellent condition (interior and exterior) is due to both the maintenance it receives and the upkeep provided by the Locke Station Interns. Equipment on this tender is all in good working condition with normal service life expectancy.

Apparatus 149 is a 1992, 3,000-gallon Pierce Pumper/Tender. This vehicle is currently not in service and is not expected to return to service. County Shops personnel recommend that the fuel be changed, and the vehicle started periodically to help maintain it while in the District's care. The County has offered the use of a pump to off-load the fuel, and we plan to follow up with their recommendation. Equipment left on this vehicle is in working order. Lieutenant Morgan will evaluate the remaining equipment and its maintenance.

The County Shops continues to be our service provider for maintenance and repairs. Their service is timely and cost effective.

INVENTORY / CONDITION OF DRAFT SITES

Chief Loudon inspected the two improved draft sites, Hwy 34 at Whispering Pines and the sheep barns on Oak Creek, that the District put in. They are in good, serviceable condition.

Flow testing will occur in the next few weeks, and staff will inspect all other sites shown as a draft site in Incident View.

The "Rural water Supply" report written in 2002 does not reflect recent improvements, such as the addition of the tender at Station 6 and the larger water tanks on our two new engines. We now have 11,000 gallons of water in tenders (was 8,000) and greater chance that the initial attack and supply engines each have 1,000 gallons on board. This brings the total on 1st alarms to 5,000 gallons 20 percent the time, 4,500 gallons 60 percent of the time, and 4,000 gallons 20 percent of the time. In 2002, the only 1,000-gallon engine was at Station 1, so the odds of having 1,500 gallons was 16 percent; or 86 percent of the time, the two engines had 1,000 gallons plus 3,000 in the tender for a total of 4,000 gallons. As older engines (500 gallon) and 142 (2,000 gallons) are replaced over time, the numbers will improve. CFD will make several recommendations regarding 146 to meet fill time and dump time standards.

INSPECTIONS

Inspections	Reinspections	Hazards Noted	Hazards Abated
106	42	416	216

PUBLIC EDUCATION

March 2008	Beavers All Access	TV spot
July 2008	Mt. view school tour	50 kids
July 2008	Benton County Fair	500
September 2008	CV Volleyball	30 kids and parents
October 2008	Open house	150 in attendance
October 2008	Little Beavers Tour	50 kids in attendance
Total		780 + TV viewers

NEWSLETTER

The rural district newsletter was mailed to District households in May. A target date of May 15 is set for mailing of the 2009 edition.

CANVASSING

Approximately 70 District households were canvassed regarding urban interface fire safety during the month of September.

EQUIPMENT INVENTORY - TENDER 146

CAB

All present and in good condition

Rechargeable flashlight
White board with marker
ABC dry chem extinguisher
Bay door opener
BLS Kit

CROSSLAY

All present and in good condition

200' X 1.5" pre-connect
1.5" fog nozzle
Dump valve extender

LEFT SIDE

All present and in good condition

Hydrant wrench
2.5" Spanner pair
LDH Spanner pair
200' X 3" Hose
2.5" Hard-suction hose
6" Hard-suction hose
5" STORZ X 6" NH

COMPARTMENT 1

All present and in good condition

Wheel chocks
(2) 2.5" Port-a-tank supply line holders
Rubber mallet
2.5" Barrel strainer
2.5" Hydrant gate
2.5" Reversible set
6" Jet siphon X 1.5" NH female
5" STORZ X 2.5" male
5" STORZ X 2.5" female
4" STORZ to 5" STORZ (Philomath adaptor)
4.5" HN to 5" STORZ (Adair adaptor)
Duct tape
Orange flagging tape
Plastic tarp for port-a-tank (12' X 14')
(2) Stop/slow signs
(2) 6V hand light
5" X 50' Hose
Pump panel chart

COMPARTMENT 2

All present and in good condition

(8) Traffic cones
5" X 12' Hose

REAR

All present and in good condition

LDH Spanner pair
2.5" Spanner pair
Hydrant wrench
5" X 25' Hose

COMPARTMENT 3

Present and in good condition

Port-a-tank

RIGHT SIDE

All present and in good condition

3" X 200' Hose

6" Hard-suction hose

2.5" Hard-suction hose

Shovel

COMPARTMENT 4

All present and in good condition

Pick head axe

Flat head axe

4" Pry bar

LDH Spanner pair

2.5" Spanner pair

Hydrant wrench

6V Hand light

Bolt cutters

5-Way manifold

Utility rope with 2 carabineers

Foot strainer

EQUIPMENT INVENTORY - TENDER 149**FRONT BUMPER**

Moved to rack in Station - in good condition

5" X 50' LDH Supply hose (Not Present)

CAB

In good condition

2 Radio headsets (*1 is present; 1 was placed on 136*)

Pittmon map book

Dry erase board with marker

MAGNETIC KEY BOX

Key lock box *Needs repair*

Spotlight *Missing*

Clipboard *Present and in good condition*

GLOVE COMPARTMENT

All present and in good condition

FireLine handbook

Disposable camera

Binoculars

De-Icer

Ice scraper

REAR CAB

2 Radio headsets (*1 present, 1 missing*)

2 Rechargeable mag-lights (*batteries do not work or will no longer charge*)

REAR CAB (Continued)

2 Litebox flashlights (*batteries do not work or will no longer charge*)

2 Portable hand lights (*1 present; 1 missing; batteries do not work or will no longer charge*)

LEFT-FRONT COMPARTMENT

Tee handle with hydrant, gas, and Vineyard Mountain keys

LEFT-MIDDLE TOP COMPARTMENT

2 Hay hooks *Good condition*

Rubber mallet *Missing*

4-lb Sledge *Good condition*

Crowbar *Good condition*

24" Bolt cutters *Good condition*

Orange flagging tape *Good condition*

Duct tape *Missing*

Caution tape *Good condition*

11 oz Bottle of silicon spray *Good condition*

Squirt bottle of anti-freeze *Good condition*

Bottle of foam *Good condition*

6V Flashlight *Missing*

Hacksaw with blades *Missing*

TOOLBOX

All present and in good condition

(2) Hose gaskets - 5"

(2) Hose gaskets - 2.5"

Steel wire

Circuit tester

Hex wrench set

Electrical tape

Teflon tape

Hasp

Lock with 2 keys

2' Chain

3/8" Drive socket

3.8" Socket extension

Chisel

Pliers

Lineman pliers

10" Crescent wrench

Vice grips

Pipe wrench

Ball-peen hammer

Crescent wrench

25' Tape measure

Utility knife

Nut driver handle

Claw hammer

TOOLBOX (Continued)

Wrench set
1/4" Drive socket set
4 Flathead screwdrivers
4 Phillips screwdrivers
3/8" Socket to 1/2" socket adapter
2" Socket extension
2 Sprinkler stoppers
Battery terminal puller
Diagonal cutter
6" Crescent wrench
Needle-nosed pliers
Channel lock

LEFT-MIDDLE BOTTOM Top Shelf

All present good condition

2.5" Double male
2.5" Double female
2" to 2.5" Reducer
2.5" Cap
2.5" Hydrant gate
2.5" to 1.5" Reducer
2.5" to 1.5" Gated wye

LEFT-MIDDLE BOTTOM (Bottom Shelf)

All present and in good condition unless otherwise noted

STORZ to 2.5" Female
6" Steamer port cap
1.5" X 50' Hose Stored in station - not on rig

LEFT OPEN

All present and in good condition unless otherwise noted

2.5" to 1.5" Reducer (chrome)
(2) STORZ wrench
(2) 2.5" Spanners
(2) 3" X 50' Supply hose Stored in station - not on rig
Hydrant wrench
14' Aluminum roofer
(3) 6" Hard suction (one w/strainer)
(2) 2.5" Hard suction
8' Pike pole
Portable halogen floodlight

LEFT-REAR COMPARTMENT

All present and in good condition unless otherwise noted

3-Gallon unleaded gas can

(2) Wheel chocks

6V Flashlight *missing*

Portable pump Stored in station - not on rig.

REAR OPEN

All present and in good condition unless otherwise noted

5" X 25' Supply hose Stored in station - not on rig

(2) 2.5" Hydrant gate

STORZ Hydrant gate

(4) STORZ wrench

(2) 2.5" Spanners

5' Pry bar *Missing*

(2) Pick head axes

TOP OPEN

All present in good condition

(2) 5-Gallon buckets of ultrasorb

(2) 5-Gallon buckets of gravel

5-Gallon bucket absorbent pads/trash bags

Push broom

Round-point shovel

Square-point shovel

Pitchfork

(2) 5-GALLON BUCKETS

All present and in good condition

Floodlight

100' Electrical cord

Junction box

(2) Pigtails

MASTER STREAM NOZZLE TIPS

All present and in good condition

(1) 3/8" Tip

(1) 1/2" Tip

(1) 3/4" Tip

Master stream base

RIGHT-SIDE FRONT COMPARTMENT

All present and in good condition

Halligan

Flat head axe

8 lb Sledge hammer

200' Pre-connected power cord

20 lb ABC extinguisher

RIGHT-SIDE OPEN

All present and in good condition unless otherwise noted

(2) 3" X 50' Supply hose Stored in station - not on rig

(2) 2.5" Spanners

Hydrant wrench

(2) STORZ wrenches

3,000-Gallon port-a-tank

24' Extension ladder Needs repair

Portable halogen floodlight

RIGHT-SIDE MIDDLE COMPARTMENT

All present and in good condition unless otherwise noted

6V Flashlight Missing

5" Low-level strainer

Port-a-tank Supply line holder

2.5" Barrel strainer

RIGHT-SIDE REAR COMPARTMENT

All present and in good condition unless otherwise noted

Metal bucket

2.5-Gallons drinking water

(2) 12' X 14' tarps

(2) Traffic wands

6V Flashlight (not present)

Sheaf of cups

(20) Flares

(10) Traffic cones Missing 4 cones

(2) Traffic signs